

UH200 汽油軟管召回更換VIN明細表

NO	TYPE	VIN	ENGINE
1	BURGMAN 200 (UH200)	MLCC91622L1650004	H405-650004
2	BURGMAN 200 (UH200)	MLCC91622L1650005	H405-650005
3	BURGMAN 200 (UH200)	MLCC91622L1650006	H405-650006
4	BURGMAN 200 (UH200)	MLCC91622L1650007	H405-650007
5	BURGMAN 200 (UH200)	MLCC91622L1650008	H405-650008
6	BURGMAN 200 (UH200)	MLCC91622L1650009	H405-650009
7	BURGMAN 200 (UH200)	MLCC91622L1650010	H405-650010
8	BURGMAN 200 (UH200)	MLCC91622L1650011	H405-650011
9	BURGMAN 200 (UH200)	MLCC91622L1650012	H405-650012
10	BURGMAN 200 (UH200)	MLCC91622L1650013	H405-650013
11	BURGMAN 200 (UH200)	MLCC91622L1650014	H405-650014
12	BURGMAN 200 (UH200)	MLCC91622L1650015	H405-650015
13	BURGMAN 200 (UH200)	MLCC91622L1650016	H405-650016
14	BURGMAN 200 (UH200)	MLCC91622L1650017	H405-650017
15	BURGMAN 200 (UH200)	MLCC91622L1650018	H405-650018
16	BURGMAN 200 (UH200)	MLCC91622L1650019	H405-650019
17	BURGMAN 200 (UH200)	MLCC91622L1650020	H405-650020
18	BURGMAN 200 (UH200)	MLCC91622L1650021	H405-650021
19	BURGMAN 200 (UH200)	MLCC91622L1650022	H405-650022
20	BURGMAN 200 (UH200)	MLCC91622L1650023	H405-650023
21	BURGMAN 200 (UH200)	MLCC91622L1650024	H405-650024
22	BURGMAN 200 (UH200)	MLCC91622L1650025	H405-650025
23	BURGMAN 200 (UH200)	MLCC91622L1650026	H405-650026
24	BURGMAN 200 (UH200)	MLCC91622L1650027	H405-650027
25	BURGMAN 200 (UH200)	MLCC91622L1650028	H405-650028
26	BURGMAN 200 (UH200)	MLCC91622L1650029	H405-650029
27	BURGMAN 200 (UH200)	MLCC91622L1650030	H405-650030
28	BURGMAN 200 (UH200)	MLCC91622L1650031	H405-650031
29	BURGMAN 200 (UH200)	MLCC91622L1650032	H405-650032
30	BURGMAN 200 (UH200)	MLCC91622L1650033	H405-650033
31	BURGMAN 200 (UH200)	MLCC91622L1650034	H405-650034
32	BURGMAN 200 (UH200)	MLCC91622L1650035	H405-650035
33	BURGMAN 200 (UH200)	MLCC91622L1650036	H405-650036
34	BURGMAN 200 (UH200)	MLCC91622L1650037	H405-650037
35	BURGMAN 200 (UH200)	MLCC91622L1650038	H405-650038
36	BURGMAN 200 (UH200)	MLCC91622L1650039	H405-650039
37	BURGMAN 200 (UH200)	MLCC91622L1650040	H405-650040

UH200 汽油軟管召回更換VIN明細表

NO	TYPE	VIN	ENGINE
38	BURGMAN 200 (UH200)	MLCC91622L1650041	H405-650041
39	BURGMAN 200 (UH200)	MLCC91622L1650042	H405-650042
40	BURGMAN 200 (UH200)	MLCC91622L1650043	H405-650043
41	BURGMAN 200 (UH200)	MLCC91622L1650044	H405-650044
42	BURGMAN 200 (UH200)	MLCC91622L1650045	H405-650045
43	BURGMAN 200 (UH200)	MLCC91622L1650046	H405-650046
44	BURGMAN 200 (UH200)	MLCC91622L1650048	H405-650048
45	BURGMAN 200 (UH200)	MLCC91622L1650049	H405-650049
46	BURGMAN 200 (UH200)	MLCC91622L1650050	H405-650050
47	BURGMAN 200 (UH200)	MLCC91622L1650051	H405-650051
48	BURGMAN 200 (UH200)	MLCC91622L1650052	H405-650052
49	BURGMAN 200 (UH200)	MLCC91622L1650053	H405-650053
50	BURGMAN 200 (UH200)	MLCC91622L1650054	H405-650054
51	BURGMAN 200 (UH200)	MLCC91622L1650055	H405-650055
52	BURGMAN 200 (UH200)	MLCC91622L1650056	H405-650056
53	BURGMAN 200 (UH200)	MLCC91622L1650057	H405-650057
54	BURGMAN 200 (UH200)	MLCC91622L1650058	H405-650058
55	BURGMAN 200 (UH200)	MLCC91622L1650059	H405-650059
56	BURGMAN 200 (UH200)	MLCC91622L1650060	H405-650060
57	BURGMAN 200 (UH200)	MLCC91622L1650061	H405-650061
58	BURGMAN 200 (UH200)	MLCC91622L1650062	H405-650062
59	BURGMAN 200 (UH200)	MLCC91622L1650063	H405-650063
60	BURGMAN 200 (UH200)	MLCC91622L1650064	H405-650064
61	BURGMAN 200 (UH200)	MLCC91622L1650065	H405-650065
62	BURGMAN 200 (UH200)	MLCC91622L1650066	H405-650066
63	BURGMAN 200 (UH200)	MLCC91622L1650067	H405-650067
64	BURGMAN 200 (UH200)	MLCC91622L1650068	H405-650068
65	BURGMAN 200 (UH200)	MLCC91622L1650069	H405-650069
66	BURGMAN 200 (UH200)	MLCC91622L1650070	H405-650070
67	BURGMAN 200 (UH200)	MLCC91622L1650072	H405-650072
68	BURGMAN 200 (UH200)	MLCC91622L1650073	H405-650073
69	BURGMAN 200 (UH200)	MLCC91622L1650074	H405-650074
70	BURGMAN 200 (UH200)	MLCC91622L1650075	H405-650075
71	BURGMAN 200 (UH200)	MLCC91622L1650076	H405-650076
72	BURGMAN 200 (UH200)	MLCC91622L1650077	H405-650077
73	BURGMAN 200 (UH200)	MLCC91622L1650078	H405-650078
74	BURGMAN 200 (UH200)	MLCC91622L1650079	H405-650079

UH200 汽油軟管召回更換VIN明細表

NO	TYPE	VIN	ENGINE
75	BURGMAN 200 (UH200)	MLCC91622L1650081	H405-650081
76	BURGMAN 200 (UH200)	MLCC91622L1650082	H405-650082
77	BURGMAN 200 (UH200)	MLCC91622L1650083	H405-650083
78	BURGMAN 200 (UH200)	MLCC91622L1650084	H405-650084
79	BURGMAN 200 (UH200)	MLCC91622L1650085	H405-650085
80	BURGMAN 200 (UH200)	MLCC91622L1650087	H405-650087
81	BURGMAN 200 (UH200)	MLCC91622L1650088	H405-650088
82	BURGMAN 200 (UH200)	MLCC91622L1650090	H405-650090
83	BURGMAN 200 (UH200)	MLCC91622L1650091	H405-650091
84	BURGMAN 200 (UH200)	MLCC91622L1650093	H405-650093
85	BURGMAN 200 (UH200)	MLCC91622L1650097	H405-650097
86	BURGMAN 200 (UH200)	MLCC91622L1650099	H405-650099
87	BURGMAN 200 (UH200)	MLCC91622L1650100	H405-650100
88	BURGMAN 200 (UH200)	MLCC91622L1650102	H405-650102
89	BURGMAN 200 (UH200)	MLCC91622L1650106	H405-650106
90	BURGMAN 200 (UH200)	MLCC91622L1650107	H405-650107
91	BURGMAN 200 (UH200)	MLCC91622L1650108	H405-650108
92	BURGMAN 200 (UH200)	MLCC91622L1650110	H405-650110
93	BURGMAN 200 (UH200)	MLCC91622L1650114	H405-650114
94	BURGMAN 200 (UH200)	MLCC91622L1650115	H405-650115
95	BURGMAN 200 (UH200)	MLCC91622L1650116	H405-650116
96	BURGMAN 200 (UH200)	MLCC91622L1650117	H405-650117
97	BURGMAN 200 (UH200)	MLCC91622L1650118	H405-650118
98	BURGMAN 200 (UH200)	MLCC91622L1650119	H405-650119
99	BURGMAN 200 (UH200)	MLCC91622L1650120	H405-650120
100	BURGMAN 200 (UH200)	MLCC91622L1650121	H405-650121
101	BURGMAN 200 (UH200)	MLCC91622L1650122	H405-650122
102	BURGMAN 200 (UH200)	MLCC91622L1650123	H405-650123
103	BURGMAN 200 (UH200)	MLCC91622L1650125	H405-650125
104	BURGMAN 200 (UH200)	MLCC91622L1650126	H405-650126
105	BURGMAN 200 (UH200)	MLCC91622L1650127	H405-650127
106	BURGMAN 200 (UH200)	MLCC91622L1650128	H405-650128
107	BURGMAN 200 (UH200)	MLCC91622L1650129	H405-650129
108	BURGMAN 200 (UH200)	MLCC91622L1650135	H405-650135
109	BURGMAN 200 (UH200)	MLCC91622L1650137	H405-650137
110	BURGMAN 200 (UH200)	MLCC91622L1650139	H405-650139
111	BURGMAN 200 (UH200)	MLCC91622L1650140	H405-650140

UH200 汽油軟管召回更換VIN明細表

NO	TYPE	VIN	ENGINE
112	BURGMAN 200 (UH200)	MLCC91622L1650141	H405-650141
113	BURGMAN 200 (UH200)	MLCC91622L1650142	H405-650142
114	BURGMAN 200 (UH200)	MLCC91622L1650143	H405-650143
115	BURGMAN 200 (UH200)	MLCC91622L1650144	H405-650144
116	BURGMAN 200 (UH200)	MLCC91622L1650146	H405-650146
117	BURGMAN 200 (UH200)	MLCC91622L1650147	H405-650147
118	BURGMAN 200 (UH200)	MLCC91622L1650148	H405-650148
119	BURGMAN 200 (UH200)	MLCC91622L1650149	H405-650149
120	BURGMAN 200 (UH200)	MLCC91622L1650150	H405-650150
121	BURGMAN 200 (UH200)	MLCC91622L1650152	H405-650152
122	BURGMAN 200 (UH200)	MLCC91622L1650153	H405-650153
123	BURGMAN 200 (UH200)	MLCC91622L1650154	H405-650154
124	BURGMAN 200 (UH200)	MLCC91622L1650155	H405-650155
125	BURGMAN 200 (UH200)	MLCC91622L1650156	H405-650156
126	BURGMAN 200 (UH200)	MLCC91622L1650157	H405-650157
127	BURGMAN 200 (UH200)	MLCC91622L1650158	H405-650158
128	BURGMAN 200 (UH200)	MLCC91622L1650159	H405-650159
129	BURGMAN 200 (UH200)	MLCC91622L1650160	H405-650160
130	BURGMAN 200 (UH200)	MLCC91622L1650162	H405-650162
131	BURGMAN 200 (UH200)	MLCC91622L1650163	H405-650163
132	BURGMAN 200 (UH200)	MLCC91622L1650169	H405-650169
133	BURGMAN 200 (UH200)	MLCC91622L1650170	H405-650170
134	BURGMAN 200 (UH200)	MLCC91622L1650172	H405-650172
135	BURGMAN 200 (UH200)	MLCC91622L1650175	H405-650175
136	BURGMAN 200 (UH200)	MLCC91622L1650178	H405-650178
137	BURGMAN 200 (UH200)	MLCC91622L1650179	H405-650179
138	BURGMAN 200 (UH200)	MLCC91622L1650180	H405-650180
139	BURGMAN 200 (UH200)	MLCC91622L1650181	H405-650181
140	BURGMAN 200 (UH200)	MLCC91622L1650182	H405-650182
141	BURGMAN 200 (UH200)	MLCC91622L1650183	H405-650183